Guy Broadwater House Accident Private

c.1900

Several frame buildings, including a two-story L-shaped farmhouse, a small auxiliary house, a garage and a bank barn, make up this farm. The inner crook of the dwelling's ell includes a diagonal entrance. Either section of the house measures three bays long by one bay deep. A porch shelters the south and east sides, which together form the facade.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME				
HISTORIC				•
AND/OR COMMON				
Guy Broadw	ater House			
2 LOCATION	J			
STREET & NUMBER	•			
	sville Rd., approx2	mile North of F	riendsville	
CITY, TOWN	approx. 12 mile north of Fi		CONGRESSIONAL DISTRICT	
CTATE	Accident vici		6th COUNTY Garrett County	
STATE Maryland				
3 CLASSIFIC	ATION			
CATEGORY	OWNERSHIP	STATUO		
DISTRICT	PUBLIC	STATUS &OCCUPIED	PRES XAGRICULTURE	ENT USE
BUILDING(S)	X PRIVATE	_UNOCCUPIED	COMMERCIAL	MUSEUM
STRUCTURE	ВОТН	WORK IN PROGRESS	EDUCATIONAL	—PARK ★PRIVATE RESIDENCE
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	
OBJECT	IN PROCESS	YES: RESTRICTED	GOVERNMENT	RELIGIOUS SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION
		XNO	MILITARY	_OTHER
NAME Gu Street & NUMBER	F PROPERTY Broadwater		Telephone #:	
	cident-Friendsville R	oad		
CITY, TOWN AC	cident <u>x</u>	VICINITY OF	STATE, Z Maryland 2	ip code 21520
5 LOCATION	OF LEGAL DESCR	IPTION	Liber #:	
COURTHOUSE,			Folio #:	
REGISTRY OF DEEDS, E	Garrett County Co	ourthouse	10110 #:	
STREET & NUMBER Thir	d and Alder Streets			
CITY, TOWN	. 1		STATE	
0akland		Mary la	and 21550	
6 REPRESEN	TATION IN EXISTI	NG SURVEYS		
TITLE				
None				
DATE		FEDERAL	_STATECOUNTYLOCAL	
DEPOSITORY FOR		EVENINE	LOCAL	
SURVEY RECORDS				
CITY, TOWN			STATE	
				



CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT

__DETERIORATED
__RUINS

MUNALTERED __ALTERED

★ORIGINAL SITE

≾GOOD __FAIR

__UNEXPOSED

__MOVED DATE____

__MOVED DATE____

GI-B-163

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Several frame buildings, including a two-story L-shaped farmhouse, a small auxiliary house, a garage and a bank barn, make up this farm. The inner crook of the dwelling's ell includes a diagonal entrance. Either section of the house measures three bays long by one bay deep. A porch shelters the south and east sides, which together form the facade.

The slate roof includes several rows of scalloped shingles. Asbestos shingles sheath the walls. A brick chimney heats the center of either section of the house. A cut stone block foundation underpins the building. A cellar entrance appears at the east end. 2/2 windows light the house. A modern shed-roofed addition covers the north side.

The auxiliary house stands about 20 feet north of the main dwelling. The true $1\frac{1}{2}$ story building presents two bays on each elevation. A porch shelters the east facade. Entrances appear on the south and east elevations. 6/6 windows light the German-sided building. An exterior brick stove-flue chimney appears at the west end.

SPECIFIC DAT	ES c.1900	BUILDER/ARCH	UITECT	
PERIOD —PREHISTORIC —1400-1499 —1500-1599 —1600-1699 —1700-1799 —1800-1899 ★1900-	ARCHEOLOGY-PREHISTORIC ARCHEOLOGY-HISTORIC AGRICULTURE XARCHITECTURE ART COMMERCE COMMUNICATIONS	REAS OF SIGNIFICANCE CH COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION ENGINEERING EXPLORATION/SETTLEMENT INDUSTRY INVENTION	LANDSCAPE ARCHITECTURE LAW LITERATURE MILITARY MUSIC PHILOSOPHY POLITICS/GOVERNMENT	RELIGION SCIENCE SCULPTURE SOCIAL/HUMANITARIAN THEATER TRANSPORTATION OTHER (SPECIFY)

STATEMENT OF SIGNIFICANCE

The diagonal entrance is a distinctive feature in this otherwise typical farmhouse.

CONTINUE ON SEPARATE SHEET IF NECESSARY


9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE	ON SEPARATE SHEET IF NECESSARY		
10 GEOGRA	PHICAL DATA		
	OMINATED PROPERTY		
ACTUACE OF THE			
VEDRAL DOL	NIDARY DESCRIPTION		<u>,</u>
VERBAL BUU	NDARY DESCRIPTION		
LIST AL	L STATES AND COUNTIES FOR PROPERTIES OVERLAPPING S	TATE OR COUNT	Y BOUNDARIES
STATE	COUNTY		
	201177		
STATE	COUNTY	•	
	NED A DED DV		
	REPARED BY		
NAME / TITLE			
ORGANIZATION	Merry Stinson, Architectural Historian	DATE	
URGANIZATION	Maryland Historical Trust/Bureau of Mines	Apr	il 1982
STREET & NUMBE		TELEPHO	
	Shaw House, 21 State Circle	(301) 269	-2438
CITY OR TOWN		STATE Maryland	21401
	Annapolis,	maryrand	217U1

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438




Accident, MD-PA USGS 7.5 minute series Scale-1:24,000 1948; photorevised 1974

Site #: G-II-B-168
Guy Broadwater House
Accident-Friendsville Rd.,
approx. .2 mile N of Friendsville Rd.



G-II-B-168
Guy Broadwater House
Garrett Co., MD
Photo: A. Burns 9 Oct. 1980
Facade - SE elev.



G-II-B-168
Guy Broadwater House
Garrett Co., MD
Photo: A. Burns 9 Oct. 1980
W elev.



G-II-B-168
Guy Broadwater House
Garrett Co., MD
Photo: A. Burns 9 Oct. 1980
Outbldg: S elev; Facade - E elev.